**BASELOAD DISPATCH PERFORMANCE**
(% EAF for Period)
LEAC Period Feb 15 - Jul 15

Cabras 1 - Air preheater issues; repair of damaged main transformer;
Cabras 2 - Boiler tube leaks; air preheater issues; boiler high water consumption
Cabras 3 - unplanned outages due to fuel oil injector/ injection issues;
Cabras 4 - Scheduled Generator Overhaul; unplanned outages due to engine high scavenging air temp;

Actual Baseload EAF
Actual Baseload EAF Avg
PUC Performance Standard